

Tenneco Minerals
A Tenneco Company

P.O. Box 2650
St. George, Utah 84770
(801) 574-3164



January 6, 1992

Utah Department of Natural Resources
Division of Oil, Gas, and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, UT 84180-1203

Attention: Wayne Hedberg

Reference: Wildlife Impact Summary - December 1991

Dear Mr. Hedberg:

During the month of December, we experienced the loss of one deer fawn. This was reported by phone to Mr. John Schijf, Conservation Officer of the Utah State Department of Natural Resources in St. George, Utah. The deer was found dead in the fresh water pond where it had apparently drowned. A brief summary of the circumstances are as follows:

During expansion of our pond and construction of a new pond it was necessary to remove the chain link fence from the west and south sides of our pond area. We installed a temporary 6' high fence around the construction area using orange plastic mesh safety netting material. Two wildlife cannons were located near the pond areas as an extra precaution.

Some problems were experienced with the temporary fence during high wind conditions. Maintenance of the fence was effected when damage became apparent. On the night of the occurrence, apparently a section of the fence was down and the cannons were not working.

RECEIVED

JAN 13 1992

DIVISION OF
OIL GAS & MINING

Sincerely,

TENNECO MINERALS COMPANY

Robert K. Wilson

Robert K. Wilson
Environmental Coordinator

RKW:bas